



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

May 30, 1991

Mr. Dwight Crossland
Western States Minerals Corp.
84 Glen Carron Circle
Sparks, Nevada 89431

Dear Mr. Crossland:

Re: Revegetation and Topsoil Deficiency at Drum Mine, M/027/007, Millard County, Utah

Discussions concerning test plot establishment and soil sampling were initiated with Mr. Richard McNeely of Western States Minerals Corp. (WSMC) in September of 1989. Those discussions resulted from the determination that a 54,200 cubic yard topsoil deficiency existed at the Drum mine and that WSMC would be responsible for alleviating the deficiency. WSMC was asked to establish revegetation test plots at the Drum site after performing soils analyses of materials found on site.

Mr. Frank Filas of WSMC performed the analyses in April of 1990 (please see attached analyses). The analyses were forwarded to the Division for our evaluation and recommendation. The following observations and requirements are based on my evaluation of the lab analyses:

1. The analyses obtained by Mr. Filas suggests that direct revegetation attempts on existing leach pads and dumps, without first topsoiling, would be futile. These materials are very saline and sodic, making it difficult for plant establishment. However, some of the waste dump material may be suitable as indicated by the analyses performed on area #7.
2. Areas/samples identified by Mr. Filas as 1, 2, 3, 4 and 7 cannot be used as soil substitutes. The salts found in these soils will not support an acceptable plant cover.
3. Areas/samples identified by Mr. Filas as 5, 6, and 8 can be used as substitute material. Areas 5, and 6 are borrow areas and area 8 is a waste dump area.

Page 2

Western States Minerals Corp.

M/027/007


May 30, 1991

The analyses indicate that a revegetation test plot program on the leached heaps and some of the waste dumps would prove unsuccessful, because of the very poor nature of the material to be used as a plant growing medium. These areas must be topsoiled with an acceptable material. We will require that WSMC go ahead with a plan that would involve topsoiling of those areas identified as having poor soil qualities either chemically poor or physically poor (very coarse texture). Such a plan would involve the identification of borrow areas. Waste dumps that have been identified as having acceptable soil qualities can be reclaimed without the addition of topsoil.

The Division suggests performing a more extensive soil analyses on those areas slated as borrow areas to ensure that poor quality soil is not used. Area #4 on Mr. Filas' list was a borrow location and some of the poorest quality material evaluated on site.

Please contact us by June 30, 1991, concerning the development of the revegetation/topsoil redistribution plan. The process of expediting this plan would be served best by establishing a meeting date to discuss the plan with Division staff.

Sincerely,

A handwritten signature in black ink, appearing to read "Holland Shepherd", written in a cursive style.

Holland Shepherd
Senior Reclamation Specialist

jb

Attachment

cc: Al Cerney, WSMC
Ed King, Jumbo Mining
Wayne Hedberg, DOGM

M027007.1

Frank Filas
Western States Minerals
4975 VanGordon Street
Wheat Ridge, CO 80033

CSU Soil Testing Lab
Room 6, Voc. Ed. Bldg.
Fort Collins, CO 80523
303-491-5061

NOTE: Your samples will be
automatically discarded 30 days
from the date on this report
unless you notify the lab to
keep the samples. Thank you.
Date: 4/4/90
Billing: 509251


Date Rec: 2/22/90

Research Analysis


Lab #	Sample ID #	Paste pH	Paste E.C. mmhos/cm	---meq/l from sat. ext.---			SAR	% Sat	---AB-DTPA---		CEC meq/100g
				Ca	Mg	Na			NO3-N	P	
*R6945	1*H	6.6	26.8	29.9	36.3	1249.6	1.2	43.4	30	52	2.5
*6946	2H	7.2	24.1	36.1	32.7	220.4	1.0	37.6	24	19	2.3
*6947	3H	9.1	58.4	2.6	2.3	795.7	1.8	505.6	32	180	4.7
*6948	4-D	7.4	69.9	181.1	132.4	634.8	0.4	50.7	30	7	2.3
ok-6949	5-D	8.3	1.3	1.3	0.2	11.8	0.1	13.4	23	8	5.0
ok-6950	6-B	8.6	1.3	1.1	0.1	12.3	0.1	15.7	26	2	3.4
*6951	7-WP	7.4	28.9	75.3	63.6	1179.1	0.3	21.5	39	55	3.1
ok-6952	8-WP	7.4	13.4	71.4	25.4	73.9	0.3	10.6	37	26	3.1

Lab #	Sample ID #	% Sand	% Silt	% Clay	Texture	% CaCO3 equiv	% Total S	Acid-Base Potential	
R6945	1	58	24	18	SL	1.3	0.31	3.3	
6946	2	67	20	13	SL	0.7	0.25	-0.8	
6947	3	40	43	17	L	3.8	0.38	26.1	
6948	4	48	26	26	SCL	24.1	0.15	236.3	
6949	5	82	8	10	LS	7.2	<0.01	72.0	
6950	6	78	8	14	SL	4.4	<0.01	44.0	
6951	7	42	25	33	CL	6.5	0.81	39.7	
6952	8	44	26	30	CL	6.4	0.74	40.9	

* See attached list for sample ID's



2/15/90



• Drillholes


Jumbo Mining Company
M/027/007
Drum Mine Site
Present Disturbance

Scale: 1" = 600'

Map Compiled December 5, 1989
Last Update: July 26, 1990



State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining



Approximately 7 miles of 6" steel pipeline with Victaulic couplers to be reclaimed.